

NS-W 选型表

NS-	商标									
	型号	产品名称								
	W-	压力传感器、变送器								
		X-	X 为所需量程， 单位为 Pa, kPa, MPa 例：100kPa, 10MPa							
			代码	综合精度						
			3	0.25%						
			1	0.1%						
			5	0.05%						
			代码	工作方式						
			A	绝压						
			G	表压（可省略）						
			代码	输出信号						
			C	0~100mV						
			I	4~20mA						
			V1	0~5V						
			V2	0~10V						
			代码	工作电压						
			1	10VDC						
			2	24VDC						
			T	特殊规格						
			代码	接线形式						
			0	电缆连接						
			2	Hirschmann 接插头						
			9	航空接插件						
			代码	螺纹接口						
			2	M20×1.5						
			4	M24×1.5						
			T	特殊规格						
NS	-	W	-10MPa	3	G	V	2	2	2	← 选型举例