

NS-K 选型表

NS-		商标										
		型号	产品名称									
		K-	负压传感器、变送器									
		X-	X 为所需量程， 单位为 kPa 例： -100kPa, -50KPa									
			代码	综合精度								
			3	0.25%								
			1	0.1%								
			5	0.05%								
			代码	工作方式								
			F	负压								
			代码	输出信号								
			C	0~100mV								
			I	4~20mA								
			V1	0~5V								
			V2	0~10V								
			代码	工作电压								
			1	10VDC								
			2	24VDC								
			T	特殊规格								
			代码	接线形式								
			0	电缆连接								
			2	Hirschmann 接插头								
			9	航空接插件								
			代码	螺纹接口								
			1	M12×1								
			2	M20×1.5								
			4	M24×1.5								
			T	特殊规格								
NS	-K	-50KPa	3	F	I	1	2	2	← 选型举例			